

R!RES;INTL 0,4;EXIT;

Division of Oil, Gas, & Mining  
Mining Report

03/20/95

MINE ID: M0270007

MINE NAME: DRUM MINE

OPERATOR: JUMBO MINING COMPANY  
 CONTACT: DAVE HARTSHORN  
 ADDRESS: P O BOX 999  
 DELTA UT 84624

PHONE: (801)864-4697

Surface Owner: BLM  
 Mineral Owner: BLM

BLM #: UTU-063447  
 Lease #:

Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr1 Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2 Sec Town Range  
 7 15.0S 10.0W

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: SUS

Acreage: 137

Status Date: / /

Minerals Mined  
 AU

DATE  
 RECEIVED

TENTATIVE APPROVAL  
 DATE

FINAL APPROVAL  
 DATE

LAST INSPECTED

07/08/83

10/03/83

11/28/83

03/09/95

BOND TYPE: U S TREASURY BILLS

BOND AMOUNT: \$\$\$\$165,000

ANNUAL REPORT YEAR: 94

	YTD	Total	DATE ISSUED:	/	/	DATE RESOLVED:	/	/
NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/	/
VIOLATIONS:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/	/
REVISIONS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/	/
AMENDMENTS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/	/

## COMMENTS:

DRUM MINE CLOSED DOWN BY THE DEPT OF ENVIRONMENTAL QUALITY FOR HEAP LEACH DUMPS LEAKING. JUMBO ATTEMPTED TO USE 2 OTHER DUMPS UNDER THE AUTHORITY OF WESTERN STATES MINERALS, BUT WSM REFUSED JUMBO ACCESS. OPERATOR TRYING TO DEVELOP A NEW HEAP LEACH FACILITY (IN PERMITTING PROCESS). HEAP LEACH #7 WAS RESEED. OPERATOR RECLAIMED (SEED) +20 ACRES DURING 1992. INSPECTION MADE SPRING OF 1993 TO BETTER FAMILARIZE DOGM & BLM W/CURRENT STATE OF SITE.MEMO DATED 4/21/93 IN FILE. INSPECTION 3/95 MEMO LISTS RECOMMENDATIONS.